

986
PAI00076

MATERIAL SAFETY DATA SHEET
FOR COATINGS, RESINS AND RELATED MATERIALS
REPLACES NPCA 1-82

REC'D OCT 27 2000

MANUFACTURER'S NAME: HERESITE PROTECTIVE COATINGS, INC.
DATE OF PREPARATION: August 26, 1998

EMERGENCY TELEPHONE NUMBERS
HERESITE 920-684-6646
CHEMTREC 800-424-9300

INFORMATION TELEPHONE NUMBER
920-684-6646

SECTION I - PRODUCT IDENTIFICATION

PRODUCT NUMBER:
PRODUCT NAME: HERESITE VR-506 FINISH
PRODUCT CLASS: Air Drying Modified Phenolic Industrial Coating
PROPER SHIPPING NAME: Combustible Liquids, n.o.s. (Paint), NA1993,
PG III

SECTION II - HAZARDOUS INGREDIENTS

INGREDIENT	PERCENT (BY WT)	OCCUPATIONAL EXPOSURE LIMITS		VAPOR PRESSURE (mm Hg)
		TLV (ppm)	PEL (ppm)	
Mineral Spirits (CAS# 64742-88-7)	35-40	100	100	1.5 @ 60°F

SECTION III - PHYSICAL DATA

BOILING RANGE 300°F - 410°F VAPOR DENSITY X HEAVIER LIGHTER THAN AIR
EVAPORATION RATE FASTER X SLOWER THAN ETHER 49.7% VOLATILE VOLUME
WEIGHT 8.8 LBS/GALLON

986

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLAMMABLE CLASSIFICATION: OSHA II FLASH POINT 104°F LEL 1.0%
DOT COMBUSTIBLE LIQUID (TCC) Mineral Spirits

EXTINGUISHING MEDIA:

X FOAM "ALCOHOL" FOAM X CO₂ X DRY CHEMICAL X WATER FOG OTHER

UNUSUAL FIRE AND EXPLOSION HAZARDS: Keep container tightly closed.

Keep away from heat, sparks, electrical equipment and open flame.

SPECIAL FIREFIGHTING PROCEDURES: Use self-contained breathing apparatus with a full facepiece operated in pressure-demand or other positive pressure mode. Use cold water to cool fire-exposed containers.

SECTION V - HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE

EYES: Contact can cause severe irritation, redness, tearing and blurred vision.

SKIN: Contact may cause irritation, defatting and dermatitis.

INHALATION: Can cause nasal and respiratory irritation, dizziness, weakness, fatigue, nausea and headache.

INGESTION: Can cause gastrointestinal irritation, nausea, vomiting and diarrhea. Aspiration of material into the lungs can cause chemical pneumonitis which can be fatal.

PRIMARY ROUTE(S) OF ENTRY: X DERMAL X INHALATION X INGESTION

EMERGENCY AND FIRST AID PROCEDURES

EYES: Flush with large amount of water, lifting upper and lower lids occasionally. Get medical attention promptly.

SKIN: Thoroughly wash exposed area with soap and water. Remove contaminated clothing. Launder contaminated clothing before reuse.

INHALATION: Remove individual to fresh air. If breathing is difficult, administer oxygen. If breathing has stopped, give artificial respiration. Keep person warm, quiet and get medical attention.

INGESTION: Do not induce vomiting. Give conscious individual a glass of milk or water. Do not give anything by mouth to an unconscious person. Get medical attention.

SECTION VI - REACTIVITY DATA

STABILITY: _ UNSTABLE X STABLE

HAZARDOUS POLYMERIZATION: _ MAY OCCUR X WILL NOT OCCUR

HAZARDOUS DECOMPOSITION PRODUCTS: By fire: CO₂, CO & various hydrocarbons.

CONDITIONS TO AVOID: Keep away from heat, sparks, electrical equipment and open flame.

INCOMPATIBILITY (MATERIALS TO AVOID): None known.

986

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Evacuate non-essential personnel. Eliminate all ignition sources. Ventilate the area. Equip clean-up crew with appropriate protective equipment. (See next section.) Stop spill at source, dike area of spill to prevent spreading. Notify appropriate authorities if necessary. Pump or scoop liquid to salvage tank or drum. Remaining liquid may be absorbed with sand, clay, earth or floor absorbent.

WASTE DISPOSAL: Waste material must be disposed of in accordance with federal, state and local environmental control regulations. Incineration is the preferred method. Empty containers must be handled with care due to product residue. Decontaminate containers prior to disposal. **DO NOT HEAT OR CUT EMPTY CONTAINERS WITH ELECTRIC OR GAS TORCH.**

SECTION VIII - SAFE HANDLING AND USE INFORMATION

RESPIRATORY PROTECTION: A NIOSH/MSHA respirator is required if the TLV of any ingredient is exceeded.

VENTILATION: Provide sufficient mechanical (general and/or local exhaust) ventilation to maintain exposure below TLV.

PROTECTIVE GLOVES: Chemical resistant gloves are recommended.

EYE PROTECTION: Safety glasses with side shields, splash goggles or face shield recommended.

OTHER PROTECTIVE EQUIPMENT/HYGIENIC PRACTICES: Cover as much exposed skin area as possible with appropriate clothing.

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Store away from heat and open flame.

OTHER PRECAUTIONS: Keep closure tight and container upright to prevent leakage.

PREPARED BY:

Steven Brunner
Technical Director
HERESITE PROTECTIVE COATINGS, INC.
P.O. Box 250
Manitowoc, WI 54221-0250